

FIELD OBSERVATION DATA

CLIENT:

PROJECT ADDRESS: Lower Manhattan

INVESTIGATION DATE: 6/17/02

INVESTIGATOR: Uday Singh, Clyde Johnson, US EPA-Mark Maddaloni

ID	analyte	Location	Observed Concentration	Units	Notes – other observations
49	Hg	47 Ann St., Apt. 7F under refrigerator	135	ng/m ³	
50	"	47 Ann St., Apt. 7F bathroom vent	67	"	
51	"	47 Ann St., 7th floor staircase (6" off floor)	38	"	
52	"	47 Ann St., 7th floor East hallway window	26	"	
53	"	47 Ann St., 7th floor hallway	114	"	
54	"	47 Ann St., baby seat (on staircase to roof)	39, 41	"	
55	"	47 Ann St., roof	28	"	
56	"	47 Ann St., elevator mechanical room	30	"	
57	"	47 Ann St., elevator shaft	25	"	
58	"	47 Ann St., dust deposits on roof	20, 22	"	dust had been exposed for 9 months
59	"	47 Ann St., bathroom vents on roof	100, 308, 316, 319, 320	"	
60	"	47 Ann St., Apt. 7R hallway	49 (floor), 30 (6' off floor)	"	

FIELD OBSERVATION DATA

CLIENT:

PROJECT ADDRESS: Lower Manhattan

INVESTIGATION DATE: 6/17/02

INVESTIGATOR: Uday Singh, Clyde Johnson, US EPA-Mark Maddaloni

ID	analyte	Location	Observed Concentration	Units	Notes – other observations
61	Hg	47 Ann St., Apt. 7R under refrigerator	130	ng/m ³	
62	"	47 Ann St., Apt. 7R kitchen cabinet	60	"	
63	"	47 Ann St., Apt. 7R washing machine	89	"	
64	"	47 Ann St., Apt. 7R behind stove	47	"	
65	"	47 Ann St., Apt. 7R baby's crib	42	"	
66	"	47 Ann St., Apt. 7R under crib	145	"	
67	"	47 Ann St., Apt. 7R radiator	118 (6" off floor), 60 (5' off floor)	"	
68	"	47 Ann St., Apt. 7R white carpet	59	"	
69	"	47 Ann St., Apt. 7R plastic toy	49	"	
70	"	47 Ann St., Apt. 7R behind couch	79	"	
71	"	47 Ann St., Apt. 7R HEPA filter	58	"	
72	"	47 Ann St., Apt. 7R Northwest window	63, 16	"	